


Size <ligne>	10 ½”
Height <mm>	5.10(FS00 4.13)
Accuracy <per Month>	±20 sec
Battery Life	2 years

*60 minutes chronograph operation per day



Battery consumption could be minimum by pulling out the stem

Balance Weight <µN.m>	Minute 0.40 Second 0.08 Small 0.02
---------------------------------	--

Featured by Shock Detection



Original Package	500pcs
-------------------------	--------



<p>FS00</p>	<p>FS10</p>
<p>FS20</p>	<p>High Hand Ver. FS03 FS13 FS23</p> <p>Parallel Push Button Ver. FS61 FS81</p>

Time measurement

Accuracy
The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

Push "A"
Start and Stop the chronograph

Setting the Time
Set CHRONOGRAPH hands to reset
Push A to reset the hands position to the ZERO position.
And continue to push A to put them forward

Push "B"
Reset the chronograph

Setting the Date
DO NOT set Date between 9:00pm - 1:00am