



Battery consumption could be minimum by pulling out the stem









<Battery Detector Function> As warning second hand steps every 2 seconds When battery becomes nearly empty. (except for Cal. 9T22/15&9U15)

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec

