

Setting the Time



# Time measurement & Winding

### Mechanical


## **Accuracy**

Measure within lapse of  $10 \sim 60$  minutes from full winding with ① posture.

#### Posture difference

Measure accuracy in below ① ~ ④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- 43 o'clock side up



#### ■ To make full-winded

| 90 / 91 | Turn the crown 40 times |
|---------|-------------------------|
| 82 / 8N | Turn the crown 40 times |
| 6T      | Turn the crown 20 times |

## **■** Winding direction



