

## JS05 JS15 JS25

# **MIYOTA**






### Featured by Shock Detection

## Clearance

Clearance changes subject to the glass, case structure, and the length of the hand.



### Original Package


500pcs


#### Time measurement


#### Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.









Reset the chronograph

Setting the Time

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position, And continue to push A to put them forward

DO NOT set Date between 9:00pm - 1:00am