

6P23 6P25 6P27 6P29

MIYOTA



Battery consumption could be minimum by pulling out the stem





Time measurement

Accuracy
The unit (gate) time of measurement must be set at "10 sec."

and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

